

WESTBOUND WATER SUPPLY CORPORATION

201 E. 8TH ST. / PO BOX 309

CISCO, TX 76437

254-442-3348

WESTBOUNDSUPPLY@ATT.NET

October 28, 2025

To Westbound WSC Customers,

Westbound WSC (PWS ID 0670027) has violated the monitoring / reporting requirements set by TCEQ in Title 30, Texas Administrative Code (30 TAC), Section 290, Subchapter F. Public water systems are required to properly disinfect water before distribution, maintain acceptable disinfection residuals within the distribution system, monitor the disinfectant residual at various locations throughout the distribution system, and report the results of that monitoring to the TCEQ on a quarterly basis.

Results of regular monitoring are an indicator of whether or not your drinking water is safe from microbial contamination.

This violation occurred in the monitoring period at the end of the second quarter of 2025 for failure to submit the disinfectant level quarterly operating report. We are taking the following actions to address this issue: The Management of Westbound will ensure due diligence to report as quickly as possible in the future.

Please share this information with all people who drink this water, especially those who may not have received this notice directly (i.e., people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

If you have questions about this matter, you may contact Dustin Jones, Executive Director, at 254-631-1030.

Posted/Delivered on: 10/28/2025